


Precision Control Indicator

SI 510 Packaging control Indicator



Feature

- Multi display(Main, P/N, Free fall, Final, Pret)
- Weighing mode : Limit mode, Packer mode
- Automatic free fall compensation function




SI 520 Quantity control Indicator



Feature

- Multi display(Main, P/N, Count, Unit weight)
- Precise auto counting/unit weight
- Weighing mode : Limit mode, Packer mode, Checker mode




SI 530 Weight check control Indicator



Feature

- Mutil display(Main, P/N, Count, Over, Under, Pass)
- Low-end type checkweigher, Laboratory tester
- Weighing mode : Photo Sensing mode, Peak Hold mode Normal checker mode



Auto Check Weigher

Tester